



सत्यमेव जयते

Government of West Bengal
Office of the Director General
West Bengal Fire & Emergency Services
13D, Mirza Ghalib Street, Kolkata – 16

Memo No.:FSR/0125186240200083

Date : 03-06-2025

From :
Director
Fire Prevention Wing,
West Bengal Fire & Emergency Services

To :
MAA KARUNAMOYEE RAKSHA KALIMATA TRUST
RS DAG NO-197,207,208 LR DAG NO-189,201,200 LR KHATIAN NO- 821,1675, MOUZA- GAZIPUR, JL NO- 50, OWN
DRIVE WAY PLOT NO- 418(P),419(P), KH NO- 2690,2729, MOUZA- RATANPUR, JL NO- 49 UNDER SINGUR II GRAM
PANCHAYET, PS- SINGUR, DIST-HOOGHLY
Sub : Fire Safety Certificate for G+IV storied Educational building at RS DAG NO-197,207,208 LR
DAG NO-189,201,200 LR KHATIAN NO- 821,1675, MOUZA- GAZIPUR, JL NO- 50, OWN DRIVE WAY
PLOT NO- 418(P),419(P), KH NO- 2690,2729, MOUZA- RATANPUR, JL NO- 49 UNDER SINGUR II
GRAM PANCHAYET, PS- SINGUR, DIST-HOOGHLY

This is in reference to your AIN 211892506300006534 dated 02-May-2025 regarding Fire Safety Certificate for G+IV storied Educational building at RS DAG NO-197,207,208 LR DAG NO-189,201,200 LR KHATIAN NO- 821,1675, MOUZA- GAZIPUR, JL NO- 50, OWN DRIVE WAY PLOT NO- 418(P),419(P), KH NO- 2690,2729, MOUZA- RATANPUR, JL NO- 49 UNDER SINGUR II GRAMPANCHAYET, PS- SINGUR, DIST-HOOGHLY

The performance of the Fire Fighting System as incorporated in the building were tested at random and found satisfactorily working condition. In view of the above this office is releasing the **Fire Safety Certificate** for occupancy of the aforesaid building.

Recommendation:

FSC with conditions to comply the following:

- (1) M.S. staircase shall be constructed as per approved plan drawing.
- (2) Underground water reservoir shall be provided as per approved plan



The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892506300006534

Jaydeep Singh Roy
Secretary
Birla Open Minds
International School

Principal
Bhijit Chakraborty
Birla Open Minds
International School

drawing.

(3) Smoke detectors shall be installed as recommended.

To up-keep the Fire Safety Measures of the aforesaid building the following safety measures need to be incorporated / maintained:

1. Driveway must be free of any type of obstruction for easy movement of Fire Appliances. No parking will be allowed on the Drive way.
2. Entrances / Exits as marked in the sanctioned plan drawing must be opened and free from any type of obstruction.
3. The Interior finish decoration of building shall be made with low flame spread material confirming to the I.S. Specification.
4. To eliminate risk of Fire Hazards, Good House Keeping both for insides and outside of the building shall be strictly maintained.
5. Existing Electrical wiring of the whole building shall have to be carefully checked for any wear and tear in them, particularly lines above false ceiling & ducts.
6. A fire control room including a closed circuit TV system shall have to be installed which observe all the floors of the building.
7. The notice of Fire Fighting and Evacuation from the building shall be prepared and displayed at all vulnerable places of the Building.
8. The employees and security staff shall be conversant with installed fire fighting equipments of the building and to operate in the event of fire and testing.
9. Mock fire practice and evacuation drill shall be performed periodically with participants of all the occupants of the building.
10. Transformer and Switch Gears room shall be protected with CO₂ or DCP Fire extinguishers confirming I.S. specifications.
11. Fire Licence shall have to be obtained for storing and processing with LPG and other highly combustible articles.
12. A crew of trained Firemen shall be maintained round the clock for fire safety of the building.
13. First Aid fire fighting system shall be provided as per I.S. specifications.
14. Arrangement shall have to be made for regular checking, testing, and maintenance of all the Fire Fighting installation in the Building to keep them in perfectly good working condition at all the times.
15. If required the old electrical lines shall have to be replaced with new lines. The cables shall always be



The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892506300006534

Payal Smita Ray
Secretary
Birla Open Minds
International School Singur

Principal
Abhijit Chakraborty
Birla Open Minds
International School

laid in M.S. conduit pipes continuously bonded to the earth.

16. Existing lift shall be treated as fire lift in case of emergency.

17. Periodical flashing of water in the Hydrants Pipe lines shall be made to maintain the efficient working performance of above mentioned system.

18. The Fire Safety audit to be conducted at regular interval and to be recorded in the Fire Prevention maintenance register.

This Fire Safety Certificate is valid for Three years and has to be renewed every after Three year from the date of issue of this letter.

Valid Upto : 01-Jun-2028

Memo No.: FSR/0125186240200083

Debjit Sinha Roy
Secretary
Birla Open Minds
International School Sinaguri

Abhijit Chakrabarty
Principal
Birla Open Minds
International School



Signature valid

Digitally Signed.
Name: ABHINAV BANDEY
Date: 03-Jun-2023 16:02:44
Reason: D-Sign
Location: E-Dist 2.0

Director

West Bengal Fire & Emergency Services

The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892506300006534